


John Deere 4320 Forward End Cover



Machining appears to be shifted to the left, as noted by the overhang of the 2 threaded plugs as shown above. Visually the plugs appear to be not machined on the center line of the cast bosses. This could explain the lack of machine clean up in the water pump mounting area.