


# 3 point YM2210D



Control Valve

## 3 point YM2210D



Control valve removed, all valves removed and inspected. Pointing to valve that contained contamination.

# 3 point YM2210D



3 pt housing

## 3 point YM2210D



3 Point completely disassembled

# 3 point YM2210D

Control valve disassembled

\* Note material found in valve



### 3 point YM2210D

Close up of valve and material found. Material looks like a back-up seal or pump gland seal.



3 pt, was resealed and reassembled and was tested and performed much better no “bounce “

## 3 point YM2210D



# 3 point YM2210D

